Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW6634/1
Work Order Type: Weatherization
Audit Name: Audit (57)

CLIENT INFORMATION

Client Name: Address:
Client ID: 12012NW6634

Alt. Client ID:

AGENCY INFORMATION

Agency: N.W.T.N.E.D.C Agency Phone: (731) 364-3228

Address: Fax:

dresden, TN Email Address:

Agency Contact: Smith, Randy Work Phone:

Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Report Run On: 5/16/2010

DOE Weatherization Assistant Version 8.5.0 Page 1 of 5

Measures

	Measure 4 DWH	l Tank Insulation			Componer	nts			Inspected
(Comment								
					Estimated	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
		NEEDS BLANKET POP OFF AND PIPE INS							
2	Labor	DHW Tank Insulation	Each	1					
	Other Detail								
Ī									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 5 do	ors and windows			Componer	its			nspected
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	doors #2(back)	Each						
	replace with steel ins.9 lite R H 32x80							
2 Doors	door#1 (front)	Each						
	weatherstrip/doorshoe /caulk							
3 Windows	windows	Each						
	w#7 needs screen and frame and #8 broken pane w#6 approx 30x18 W-1 needs screen and frame and has broken pane approx 31x24							
Other Detail			1			1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Report Run On: 5/16/2010

Measure 6 Flo	or Ins. R-19			Componen	ts 1			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	912					
	Add approx 912 sqft of R- 19 to floor							
2 Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	912					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
	Monitor is Needed			Componen				Inspected
Measure 7 CO Comment				Estimated	<u> </u>		Actual	
Measure 7 CO Comment # Material / Labor	Description / Comment	Units	Qty	•		Qty		Inspected Total
Measure 7 CO Comment	Description / Comment	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Measure 7 CO Comment # Material / Labor 1 Health and Safet	Description / Comment			Estimated	<u> </u>	Qty	Actual	
Measure 7 CO Comment # Material / Labor 1 Health and Safet Items	Description / Comment y CO monitor	Each	1	Estimated	<u> </u>	Qty	Actual	
Measure 7 CO Comment # Material / Labor 1 Health and Safet Items 2 Labor	Description / Comment y CO monitor	Each	1	Estimated	<u> </u>	Qty	Actual	
Measure 7 CO Comment # Material / Labor 1 Health and Safet Items 2 Labor	Description / Comment y CO monitor	Each	1	Estimated	<u> </u>	Qty	Actual	
Measure 7 CO Comment # Material / Labor 1 Health and Safet Items 2 Labor	Description / Comment y CO monitor	Each Hour	1	Estimated	<u> </u>		Actual	

		Improper Venting of Ba aust Fan	throom		Componer	its			Inspected
C	omment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1					
		Vent bath fan out thru roof							
2	Labor	Labor	Hour	1					
C	Other Detail								
		·	,	Measur	e Sub Total:			Sub Total:	
	Field Notes:								
L									
			Work O	rder Gra	nd Total:		Gran	d Total:	